

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	758	(bond or bonding or solder or soldering or braze or brazeing or join or joining) near (mark or marks)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 12:17
L3	55	1 and (groove or grooves or grooved or channel or channels or passage or passages or passageway or passageways) with (bond or bonding or solder or soldering or braze or brazeing or join or joining)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 12:18
L4	90843	(rotary or rotation \$5) near (disc or discs or disk or disks)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 12:20
L5	4	4 and (bond or bonding or solder or soldering or braze or brazeing or join or joining) near (mark or marks)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 12:20
L6	1267	4 and (annular\$5) near2 (recess or recess or depression or depressions)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 12:21

L7	28	4 and (annular\$5) near2 (recess or recess or depression or depressions or groove or grooves or channel or channels or passage or passages or passageway or passageways) with (bond or bonding or solder or soldering or braze or brazing or join or joining)	US_PGPUB; USPAT; USOOR; FFPS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 12:26
L8	382881	(rotary or rotation \$5) near (shaft or shafts)	US_PGPUB; USPAT; USOOR; FFPS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 12:27
L9	5	8 and (bond or bonding or solder or soldering or braze or brazing or join or joining) near (mark or marks)	US_PGPUB; USPAT; USOOR; FFPS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 12:28
L11	383	(bond or bonding or solder or soldering or braze or brazing or join or joining) near (hole or holes or via or vias or aperture or apertures) with (shaft or shafts)	US_PGPUB; USPAT; USOOR; FFPS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 12:30
L12	2	11 and (bond or bonding or solder or soldering or braze or brazing or join or joining) near2 (mark or marks)	US_PGPUB; USPAT; USOOR; FFPS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 12:30
L14	7	(first) adj (bond or bonding or solder or soldering or braze or brazing or join or joining) adj (mark or marks)	US_PGPUB; USPAT; USOOR; FFPS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 12:34

L15	3	14 and (second or secondary) adj (bond or bonding or solder or soldering or braze or brazing or join or joining) adj (mark or marks)	US_PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 12:34
L16	87	3 or 5 or 7 or 9 or 12 or 15	US_PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 12:35

9/24/2008 12:42:29 PM

C:\Documents and Settings\kstoner\My Documents\EAST\Workspaces\i'mback.wsp